














MONTÁŽNÍ NÁVOD

Parts List:

A x5ks 	B x1ks 	C x1ks 	D x1ks 	E x1ks 	F x2ks levá podruka pravá podruka 	
G x1ks 	① x4 ks : 1/4 x2"	② x2ks 1/4 x 1-5/8"	③ x3ks 5/16 x 3/4"	④ x2ks 1/4 x 1-1/4"	⑤ x2 ks 1/4 x 1"	⑥ x1ks  M5

Postup

Krok 1 	Krok 2 ④x2ks ⑤x2,ks 	Krok 3 ①x4ks ②x2,ks 
Krok 4 ③x3ks 	Krok 5 	Krok 6 